

TEST REPORT

 Report No.:
 HC20122A/2017

 Page:
 1
 of
 7

 Date:
 March 3, 2017

VECOW CO., LTD. 12 F., NO. 111, ZHONGCHENG RD., TUCHENG DIST., NEW TAIPEI CITY, TAIWAN, R.O.C.

The following merchandise was submitted and identified by the vendor as:

Product Description:Fanless Embedded SystemStyle/ Item No.:ECS-9000-PoER/ No.1Quantity:Total 1 setTesting Period:Mar. 2, 2017

We have tested the submitted sample(s) as requested and the following results were obtained: <u>Test Required:</u> (According to client's test specification, please see following sheets in detail.)

1. Random Vibration Test

2. Mechanical Shock Test

Test Results : -PLEASE SEE ATTACHED SHEETS-

Signed for and on behalf of SGS TAIWAN Ltd.

Hank Chiou Supervisor

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <u>www.sqs.com/terms and conditions.htm</u> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <u>www.sqs.com/terms - edocument.htm</u>. Attention of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction unawful and offenders may be prosecuted to the fullest extent of the law.

> SGS Taiwan Ltd. 台灣檢驗科技股份有限公司___

No.31, No.33, No.35, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五權路 31 號, 33 號, 35 號 No.134, Wu Kung Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五工路 134 號

t (886-2) 2299-3279 f (886-2) 2299-9558



TEST REPORT

Report No.:	HC2	20122A/	2017
Page:	2	of	7

1. Random Vibration Test:

Test	Eq	ui	pm	ent:	

Name	Brand	Model	Serial No.
Vibration Tester	King Design	EM-800F2K-50N120	RU104080389
Controller	Dactron	COMET 200	10539718
Control Accelerometer	PCB	353B34	143549

Lab Environmental Conditions:

Ambient temperature:	<u>(25 ± 3) °C</u>
Ambient humidity:	<u>(55 ± 20) % RH</u>

Test Method/ Specification:

Test method:	<u>IEC 60068-2-64</u>	4, Edition 2.0: 200	<u>)8</u>	
Sample condition:	Operating (exec	ute "BurnIn Test'	<u>')</u>	
Wave form:	Random			
Frequency:	<u>(5 ~ 500) Hz</u>			
	Frequency (Hz)	Left Slope (dB/Oct.)	PSD (G ² /Hz)	Right Slope (dB/Oct.)
	5		0.05	0
	500	0	0.05	—
	⇒ equivalent	t to 5.0 G _{rms}		
Direction:	X, Y, Z axes (se	e photo 3 ~ 5)		
Duration:	<u>30 minutes/ axis</u>	<u>s</u>		

- Examine the appearance of specimen(s) by visual check and perform functional check after this test.
- Functional check: Turn on the power of specimen then examine the test program "BurnIn Test" could work normally or not.

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,可時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <u>www.sqs.com/terms and conditions.htm</u> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <u>www.sqs.com/terms - edocument.htm</u>. Attention of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

No.31, No.33, No.35, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五權路 31 號, 33 號, 35 號 d. No.134, Wu Kung Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五工路 134 號

 SGS Taiwan Ltd.
 No.134, Wu Kung Road, N

 台灣檢驗科技股份有限公司____t (886-2) 2299-3279

f (886-2) 2299-9558



TEST REPORT

Report No.:	HC	20122A/	2017
Page:	3	of	7

Specimen:

Style/Item No.: Quantity: ECS-9000-PoER/ No.1 Total 1 set

Test Result:

Check Item Style/ Item No.	Appearance check (Visual check)	Functional check
ECS-9000-PoER/ No.1	No visible damage	Normal

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <u>www.sqs.com/terms and conditions.htm</u> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <u>www.sqs.com/terms - edocument.htm</u>. Attention of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document document approval of the Company. Any unauthorized alteration, forgery or falsification of the alternated to the fullest extent of the law.

No.31, No.35, No.35, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五摧路 31 號, 33 號, 35 號 No.134, Wu Kung Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五工路 134 號

SGS Taiwan Ltd. 台灣檢驗科技股份有限公司_

t (886-2) 2299-3279 f (886-2) 2299-9558



TEST REPORT

Report No.:	HC20122A/2017			
Page:	4	of	7	

2. Mechanical Shock Test:

Test Equipment:

Name	Brand	Model	Serial No.
Shock Test System	LANSMONT	65-81 TTSII	M-13418
Data Acquisition & Analysis System	LANSMONT	103570-2-В	0503-73
ICP Accelerometer	PCB	353B14	79347

Lab Environmental Conditions:

Ambient temperature:	(<u>25 ± 3) °C</u>
Ambient humidity:	(<u>55 ± 20) % RH</u>

Test Method/ Specification:

Test Method:	IEC 60068-2-27, Edition 4.0: 2008
Sample condition:	Operating (execute "BurnIn Test")
Pulse shape:	<u>Half-sine</u>
Acceleration:	<u>50 G</u>
Pulse duration:	<u>11 ms</u>
Shock direction:	<u>6 faces ($\pm X$, $\pm Y$, $\pm Z$ axes, see photo 6 ~ 11)</u>
No. of shock:	3 shocks/ axis (total 18 shocks)

t (886-2) 2299-3279

- Examine the appearance of specimen(s) by visual check and perform functional check after this test.
- Functional check: Turn on the power of specimen then examine the test program "BurnIn Test" could work normally or not.

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,可時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <u>www.sqs.com/terms and conditions.htm</u> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <u>www.sqs.com/terms - edocument.htm</u>. Attention of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

No.31, No.35, No.35, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五權路 31 號, 33 號, 35 號 No.134, Wu Kung Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五工路 134 號

SGS Taiwan Ltd. 台灣檢驗科技股份有限公司_

f (886-2) 2299-9558



TEST REPORT

Report No.:	HC	20122A/2	2017
Page:	5	of	7

Specimen:

Style/Item No.: Quantity: ECS-9000-PoER/ No.1 Total 1 set

Test Result:

Check Item Style/ Item No.	Appearance check (Visual check)	Functional check
ECS-9000-PoER/ No.1	No visible damage	Normal

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <u>www.sqs.com/terms and conditions.htm</u> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <u>www.sqs.com/terms - edocument.htm</u>. Attention of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document document approval of the Company. Any unauthorized alteration, forgery or falsification of the alternated to the fullest extent of the law.

No.31, No.33, No.35, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五摧路 31 號, 33 號, 35 號 No.134, Wu Kung Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五工路 134 號

SGS Taiwan Ltd. 台灣檢驗科技股份有限公司_

t (886-2) 2299-3279 f (886-2) 2299-9558



TEST REPORT

Report No.:	HC	20122A/	2017
Page:	6	of	7



Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <u>www.sqs.com/terms and conditions.htm</u> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <u>www.sqs.com/terms - edocument.htm</u>. Attention of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document document approval of the Company. Any unauthorized alteration, forgery or falsification of the alternated to the fullest extent of the law.

No.31, No.33, No.35, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五摧路 31 號, 33 號, 35 號 No.134, Wu Kung Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五工路 134 號

SGS Taiwan Ltd. 台灣檢驗科技股份有限公司_


t (886-2) 2299-3279 f (886-2) 2299-9558



TEST REPORT

Report No.:	HC2	20122A/	2017
Page:	7	of	7

Test Photos -- continued:



— The End of Test Report — —

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <u>www.sqs.com/terms and conditions.htm</u> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <u>www.sqs.com/terms - edocument.htm</u>. Attention of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document document approval of the Company. Any unauthorized alteration, forgery or falsification of the alternated to the fullest extent of the law.

No.31, No.33, No.35, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五摧路 31 號, 33 號, 35 號 No.134, Wu Kung Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五工路 134 號

SGS Taiwan Ltd. 台灣檢驗科技股份有限公司_

t (886-2) 2299-3279 f (886-2) 2299-9558